User:

Wednesday, 17/09/2008 2:42:13 PM

Julie Lecocq

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number**

: 42073 : 13591

P.O. Number

This Issue

: 17/09/2008

S.O. No. :

Prsht Rev. : NC First Issue

: //

: R&D THERMOFORMING Type

Part Number

Drawing Name

: D38233 D38233

Drawing Number Project Number

Drawing Revision

: PROTOTYPE : Kydex 6185 (TBD)

: REAR OVERHEAD CENTER

Material **Due Date**

: 03/10/2008

Qty:

Each

1 Um:

Written By

Previous Run

Checked & Approved By Comment

: Est. A

Additional Product



PROTOTYPE

Job Number:



Seq. #:

1.0

Description:

HAND FINISHING THERMOFORMING



Comment: HAND FINISHING THERMOFORMING

1) Machine set up

M 109298

2.0



Comment: HAND FINISHING THERMOFORMING

1) Cut sheet to required blank size

81,90,80

3.0

THERMOFORMING

THERMOFORMING MACHINE





Comment: THERMOFORMING MACHINE

Thermoform as per Dwg. D3823-3 and folio (FTA 9110 Prototype) using tool DT 9110

Dwg. Rev. N/A

M 08.09.18

4.0

QC2





Comment: INSPECT PARTS AS THEY COME OFF MACHINE

Visually inspect for proper formation of each part

of. 08.09.18.

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	By Date Qty Approval Chief Eng / Prod Mgr QC							
		·								
		·	.							
Part No:		PAR #: Fault Category:	NCR: Yes	No DQ	A:	_ Date: _				

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
	STEP	Description of NC		Corrective Action Section B						
DATE		Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector		
	į.				•					

NOTE: Date & initial all entries

Wednesday, 17/09/2008 2:42:13 PM Data: Julie Lecoca **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: REAR OVERHEAD CENTER** Job Number: 42073 Part Number: D38233 Job Number: Seq. #: **Machine Or Operation:** Description: 5.0 QC8 SECOND CHECK Comment: SECOND CHECK 6.0 HAND FINISH TH HAND FINISHING THERMOFORMING Comment: HAND FINISHING THERMOFORMING 0809 18 1) Trim to Finished Dimensions QC2 7.0 INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE Check dimensions to ensure conformity to drawing tolerances. 8.0 QC5 INSPECT WORK TO CURRENT STEP pt 0.12.16 Comment: INSPECT WORK TO CURRENT STEP 9.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 10.0 QC21 FINAL INSPECTION/W/O RELEAS Comment: FINAL INSPECTION/W/O RELEASE Job Completion 00751 A MIL

Dart Aerospace Ltd	D	art	Aer	osp	ace	Ltd
--------------------	---	-----	-----	-----	-----	-----

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	•	PAR #:	Fault Cate	egory:	NCR: Yes	No DO	A:	Date: _		
Resolution:			Disposition: G			QA: N/C Closed: Date:				
NCR:		1	WORK ORD	ER NON-CONFORMA	NCE (NC	R)				
DATE	STEP	Description of NC	Corrective Action Section B		n B Sign		ification	Approval	Approval	
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Date		tion C	Chief Eng	QC Inspector	
			:							
					,					

NOTE: Date & initial all entries